



BISS C INTERFACE CERTIFICATE OF COMPLIANCE

Certificate Number BCM-4.05-001

Report Reference BCM-4.05-001-R

Issue Date 2022-04-21

Issued to Baumer IVO GmbH & Co. KG

Bodenseeallee 7 78333 Stockach Germany

This certificate confirms that representative samples of

ROTARY POSITION SENSORS

as specified below

have been investigated by ARTESON in accordance with the Specification indicated on this Certificate. Approval is hereby granted of marking of these devices with



Specification BiSS Interface Protocol Description (BiSS C) Rev C6

BiSS C Certification Master V4.05

Additional Information See websites of BiSS Association e.V. at biss-interface.com and

ARTESON at <u>arteson.com</u> for additional information.

Dr. Marc Scherer, Director BiSS Certification Program ARTESON INGENIEURE GbR, Hechingen, Germany

Any information and documentation involving the Compliant BiSS Device Mark are provided on behalf of BiSS Association e.V. or ARTESON INGENIEURE GbR.

The certificate does not constitute or imply any guarantee as to the usability or safety of the related BiSS Device within its application. The section "Representation and Liability" of the BiSS Device Manufacturing Agreement (BDMA) applies to the certification services accordingly. Any other liability is excluded with exemption of any liability based on the German Product Liability Act, gross negligence, fraud, or if a party's negligent acting results in death or injury to life, limb or health.

For questions, please contact ARTESON at arteson.com





BISS C INTERFACE CERTIFICATE OF COMPLIANCE

Certificate Number BCM-4.05-001

Report Reference BCM-4.05-001-R

Issue Date 2022-04-21

List of Tested Products

This is to certify that representative samples of the following product(s) were tested according to the requirements of the specification indicated on this certificate.

1. ROTARY POSITION SENSOR

Model Family: Generation 20 Essential Absolute
Sample Type ID: EN580E.ML-xxxx.xxxB1.13120.H.xxxx

4. Sohn

Serial-ID: P044.72.X-0770-5602 / MASTER_MNF_512_13ST_12MT_BISS_trig_BP3_V1.0.0

Comment: no EDS implemented

Issues to be fixed for production release: none

Date

Examiner